ECS Configuration Change Request

CCR No. 97-0794	**Logged Date** 5/15/97	**Rev.** -	**Request Type** CCR

Priority Routine ☐ Urgent ☒ Emergency ☐	**Affected Release** A	**Change Class** II

Title   Update Pre-Release B Testbed DAAC Software Environment Baseline (Doc: 420-TR-002-018)

Documents Affected	**Source Nos** (RID, NCR, Action Item, GSFC CCR, etc.) **or Tech Reference**

RTM Change ☐   **Start New Baseline** ☐

Problem
1. Update IDL to 4.01b
2. Include the following to the baseline:
- SDP Toolkit 5.1.1 a) with file path length fix b) non-HDF metadata fix
- HDF-EOS 1.5 for Sun and SGI
- EoSView 2.3 for Sun and SGI
- DB accessory with schema browser 1.0 for Sun

Proposed Solution
See attachment

Impact Analysis:

Organizations Affected:

BOO ☐	Contracts ☐	ECS Chief Eng ☐	FOS ☐	M&O ☐
Procurement ☐	QO ☐	Rel. Dev ☐	Rel. A ☒	Rel. C ☐	SCDO Arch. ☐
Science Off ☐	Security ☐	Subcontrct ☐	Sys. Eng ☐	Sys Verf Acpt ☐

Cost:	None ☒	Small ☐	Medium ☐	Large ☐
		(Not exceeding $100,000)	($100,000 to $500,000)	(Over $500,000)

Schedule: None ☒   Other

   Additional LOC _____   Man-Months _____

   Materials

Originator Evan Winston	Evan Winston	5/15/97
	Signature	Date

Office Pre B Testbed Office Manager	Narayan Prasad	5/15/97
	Signature for Rel A Manager	Date

Disposition   Approved ☒   Approved w/Comment ☐   Forward ☐   Disapproved ☐

Comments:

CCB Chairperson	Narayan Prasad	5/15/97
	Signature	Date

CM01OC96   *ECS*